


TAGA:

EPA conducted air sampling using the Trace Atmospheric Gas Analyzer (TAGA) on April 3, 2019 at the KMCO Inc. facility in Crosby, Texas. The TAGA analyzed the air samples for benzene, toluene and xylene. The TAGA air sampling results were compared to the Texas Commission on Environmental Quality (TCEQ) short-term Air Monitoring Comparison Values (AMCVs) and found no exceedances of the short-term AMCVs for benzene, toluene and xylene.




Substance	CAS #	Short-term AMCV Health (ppb)
benzene	71-43-2	180
m/p-xylene	179601-23-1	1700
o-xylene	95-47-6	1700
toluene	108-88-3	4000

Legend

- SITE LOCATION
- RESULTS BELOW AMCVs

**TAGA MONITORING MAP**
KMCO INC EXPLOSION
16503 RAMSEY RD
CROSBY, HARRIS COUNTY, TEXAS

REPORTING PERIOD #02
4/2/2019 1500 - 4/3/2019 1200



For Official Use Only



EPA GIS

Printed: 12:55:26 PM 4/3/2019